

<- Back

Forward ->

Document ID# 1044183
2003 Chevrolet Chevy Suburban - 4WD

Print

Quad Steering Inoperative, DTC Code C0550 #PI00196A - (Oct 3, 2002)

Quad Steering Inoperative, DTC Code C0550

When servicing the vehicle with the VIN you entered, the following diagnosis might be helpful if the vehicle exhibits the described symptoms.

Condition/Concern:

Quad steering (NYS) inoperative with DTC C0550. Concern will return after clearing code; may be immediate or intermittent.

Recommendation/Instructions:

Inspect for mega fuse 125A at underhood fuse holder wire loose at stud prior to replacing the rear wheel steering control module. It may be possible for circuit 1042 13 red wire to be loose at stud. Re-torque connection and test vehicle.

Please follow this diagnosis process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed. If these steps do not resolve the condition, please contact GM TAC for further diagnostic assistance. This diagnostic approach was developed for the vehicle with the VIN you entered and should not be automatically be used for other vehicles with similar symptoms.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT
VOLUNTARY
TECHNICIAN
CERTIFICATION

© Copyright General Motors Corporation. All Rights Reserved.

<- Back

Forward ->

Document ID# 1044183
2003 Chevrolet Chevy Suburban - 4WD

Print